

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index: F10

Northwest 1/16 Corner Section 9, T.4S., R.35E., W.M.

This township was subdivided by Moore in 1884.
He did not set the 1/16 corners at that time.

1	DIAGRAM	1
1	ORLS 852	1
1	1	1
1	NW ---S9	1
1	16	1
1	+	1
1	1993	1
1	T4S R35E	1
1	WALS 13922	1
1		1

Description of corner evidence found:
None

Description of monument and accessories I established to perpetuate the original location of this corner:

In the position for the North 1/16 corner, determined as per 1973 BLM Manual instructions and the original locations of the north, south and east quarter corners and the northwest and southwest corners of section 9, I set a 5/8" x 30" rebar with 2" diameter aluminum cap stamped as shown in the diagram above.

From which, I marked the following witness trees:

A 9" dbh Douglas Fir bears N82°30'E, 14.0', scribed NW1/16 S9 BT.

A 23" dbh Douglas Fir bears S21°15'W, 10.9', scribed NW1/16 S9 BT.

An aluminum washer stamped RLS 852 is nailed between the letters B and T on each new tree. All the BT's have BT signs attached.

This work was done June 24, 1993.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

David L. Haddock

**OREGON
JULY 12, 1988
DAVID L. HADDOCK
852**

Office of _____ County of _____
State of _____, I hereby certify that the within instrument was filed
in this office for record on the _____ day of _____, 19____.

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	<u>9/1/93</u>
Date Filed	<u>9/10/93</u>
By	<u>[Signature]</u>
File No.	<u>043-1993</u>