
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not set by original GLO Survey.

No subsequent monumentation of this corner found in the Union County monumentation records.



DESCRIPTION OF CORNER EVIDENCE FOUND:

Found no evidence of any monument representing this corner.

See Survey Number 032-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, from which:

NEW BEARING TREES:

A 5" diameter Tamarack bears S $40^{\circ}E$, a distance of 37.97 feet, marked X BT. A 7" diameter White Fir bears S $8^{\circ}W$, a distance of 28.41 feet, marked CS 1/16 S5 BT.

Set a steel fence post approximately 2 feet North.

I hereby certify that the corner was monumented on October 21, 1997.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OREGON
AND 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 1998

GRIFFITH & SIAC C TIN R 39 E THE TENTE OF TH

UNION COUNTY SURVEYOR Date Received 11-4-97 Date Filed 11-4-97 Filed By 4-97 File Number 051-1997R

I used a magnetic compass and steel tape in the establishment of the accessories to this corner. I used a magnetic declination of 18° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.