Dependent Resurvey of a Portion of the Subdivisional Lines, T. 1 S., R. 38 E., Willamette Meridian, Oregon

FEET

- An iron rod, ½ in. diam., firmly set, flush with the ground for a reference monument, bears N. 13° 00' 00" E., 80.1 ft. dist., with plastic cap mkd. BGA MARKER.
- A pine, 29 ins. diam., bears S. 63° E., 46.7 ft. dist., with fragmentary scribe marks visible on upper blaze and a healed lower blaze.
- A pine, 28 ins. diam., ears S. 68%° W., 47.6 ft. dist., with fragmentary scribe marks visible on upper blaze and a healed lower blaze.
- An iron rod, 5/8 in. diam., firmly set, flush with the ground for a reference monument, bears N. 31° 04′ 03" W., 38.2 ft. dist., with plastic cap mkd. BGA SUPVEY MARKER.

Corner is located W., 5 ft. dist. from the center of End Road, graveled, 30 ft. wide, extending N. and S.

The $\frac{1}{4}$ sec. cor. of secs. 16 and 21 was searched for but not found.

From this same point, the $\frac{1}{4}$ sec. cor. of secs. 18 and 19, bears N. 89° 13' 30" W., 7912.93 ft. dist., determined at record bearing and distance from the remains of the original NE. bearing tree

- A partially decayed tamarack stump, bears N. 30° E., $4.0~\rm{ft.}$ dist., with tamarack trunk, 10 ins. diam., alongside, with scribe marks $1/4~\rm{S}$ BT visible on open blaze.
- A partially decayed trunk, 10 ins. diam., species indeterminate, was found laying on the ground, with fragmentary scribe marks visible on open blaze. The original position could not be determined. (Record, tamarack, South, 9.9 ft.)

At the corner point

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 27 ins. in the ground, in a collar of stone, with brass cap mkd.

N-3

UNION COUNTY
SURVEYOR

Date Received 6/2/11

Date Filed 6/23/11

By R. Roguson Deputy

File No. 012 - 2011 R

FEET

from which new bearing trees

- A fir, 24 ins. diam., bears N. 18%° E., 28.4 ft. dist., mkd. 1/4 S18 BT.
- A fir, 19 ins. diam., bears S. 75%° E., 13.5 ft. dist., mkd. 1/4 S19 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Search was made for all intervening corners. None were found.

1° 05' 36" W., bet. secs. 16 and 17.

Over broken E. slope, through fir, tamarack, and pink timber with hyderate to dense undergrowth.

2653.78

The ¼ Sec. cor. of secs. 16 and 17, perpetuated by Duane I. Graffith, Registered Professional Land Surveyor No. 644, in 1981, from original evidence no longer visible, recorded in the Union County survey records, survey file No. 48-81, monumented with an aluminum post, 2½ ins. diam., firmly set, projecting 1 No. above a collar of stone, with aluminum cap mkd.

from which the remains of bearing trees mkd. by Griffith

- A fir, 20 ${\rm Ans.}$ diam., bears N. 67% E., 39.1 ft. dist., with healed double blazes.
- A rook hole, bears N. 17° W., 17.8 f. dist., with uprooted pine, 15 ins. diam., alongside, with fragmentary scribe marks visible on partially healed double blazes.

N - 3

UNION COUNTY
SURVEYOR

Date Received 6/12/11

Date Filed 6/23/11

By R. ROBINSIN, DEPUTY

File No. 012-2011%