CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-03

History of original corner establishment:

None.

DIAGRAM

T1N R41E

₹\$6 T1S R41E

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is marked:

Corner set by proportioning.

I set a 2½"x30" aluminum capped aluminum pipe rising 21" in a mound of stones. Set steel fencepost 3 ft. West.

T1N R41E ⅓\$6 T1S R41E RLS1848 1986

New BT's:

A 7" P. Pine bears S44½°E, 69.5 ft.,

blazed&scribed: \\$56BT

An 8" P. Pine bears S73°W, 7.5 ft.,

blazed&scribed: ⅓S6BT

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. A 3" brass disk stamped "RLS 1848" was nailed to the lower ends of the blazes.

Where 6200600 crosses USFS boundary follow posted line east uphill 300 ft. to corner on open NW'ly slope.

Compass Declination: 19½°E

Jeremy Sutton Witness:

I hereby certify that the above described corner monument and/or accessories were established as hereon described on Oct. 16, 1986.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> **OREGON** JULY 13, 1979
>
> B. A. SUTTON
> 1 8 4 8

UNION COUNTY **SURVEYOR**

Date Received 12-5-8C

Dat Filed 12-5-80

File No. 301-86 R

Office of	County of
	hereby certify that the within instrument was filed in this office
for record on the day of	, 19
•••••	by
(COUNTY OFFICIAL)	

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Note:

This corner was previously established incorrectly in Survey of Record File No. 301-86R, recorded on December 5, 1986 The monument described therein has been removed and placed as described below:

Index File No. A-03

DIAGRAM

TlN R41E

1/4°56

TlS R41E

Description of corner evidence found:

Found a 2.5" aluminum capped aluminum pipe marked: Found steel fence post 3 feet South.

TlN R41E

1/4 S6 T1S R41E RLS 1848 1986

From the corrected corner position, Bearing trees found:

An 8.5" Ponderosa Pine bears S87 1/2°W, 55.8 Ft., blazed&scribed 1/4S6BT A 7' dead standing P. Pine bears S0 1/4°E, 49.8ft, blazed&scribed 1/4S6BT

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is marked:

Corner set by proportioning.
I set a 2 1/2"X30" aluminum capped aluminum
pipe rising 21" in a mound of stones.
Set a steel fencepost 3 Ft. West in mound of stones.

1/4°56 T1S R41E RLS 1848 1987

TlN R41E

New BT:

A 7.5" Ponderosa Pine bears S49 3/4°E, 105.9 ft., blazed & scribed: 1/4S6BT.

Painted blazes and attached signs as per <u>Standard Specifications</u> <u>For Cadastral Surveys</u>, USFS Region 6, March 1982. A 3/4" brass <u>disk stamped "RLS 1848"</u> was nailed to the lower end of the blaze.

Where 6200600 crosses USFS boundary follow posted line east uphill 300 ft. to corner on open NW'ly slope.

Compass declination: 19 1/2°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on August 12, 1987

REGISTERED PROFESSIONAL LAND SURVEYOR

M

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

UNION COUNTY
SURVEYOR

Date Received 1-25-88

Date Filed 1-26-88

Glassite Deat

File No. 54-88 R

Office of	County of
State of, / hereby certif for record on the day of	y that the within instrument was filed in this office
	by
	(DEPLITY)