History of original corner establishment:

Corner established in 1873 by J. Hurlburt, under General Land Office Contract No. 201. Surveyor General's records state: Mark basalt stone about $36 \times 24 \times 24$ and about 24 in. in ground and make stone mound 2 ft. high for 1/4 Sec. Cor.

Index	File No. P-5	
DIAGRAM		
T3S	R36E	
1/4		
S19	S20	

Description of corner evidence found:

A diligent search was made and no evidence could be found of the corner.

Description of monument and accessories I established to perpetuate the original location of this corner: At a point established by single proportion measurement set $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap stamped: Set pipe 6" in ground to rock with mound of stone to cap.

R36E **T3S** WM 1/4 **S20** 1979 OR PLS 1294

From which: A P. Pine 16" in dia. bears N18°E, 106.5 ft., scribed 1/4 S20 BT. A P. Pine 22" in dia. bears N68°W, 150.9 ft., scribed 1/4 S19 BT. Attached 54-3 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red. Attached 54-2 and 54-4 signs to metal fence post 5' South of corner. Attached 54-2 sign to metal fence post 5' East of corner.

> I hereby certify the above corner monument was reestablished as herein described on November 21, 1979.

> > Witnesses:

G. Wagoner

R. Orton M. Wagoner

D. Allen

PROFESSIONAL AND SURVEYOR OREGON

REGISTERED

Office of County Surveyor State of Oregon	County of Union	HOWARD L. PERRY
State of Oregon , I hereby certify that	nt the within instrument was filed in	this office
for record on the day of		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
Form R6-7100-57 (9/71)		Date Received
		Date Filed

UNION COUNTY SURVEYOR

Date Received 10-8-87

Date Filed 10-12-87

By G. LANGLITZ DORTH

File No. 142-87 R

OREGON CORNER RESTORATION FORM

Section 20 Township 3S Range 36E

County Union

Corner Designation

Quarter Corner

Date 7-14-87

REFER TO SURVEY 29-87

X Condition Report Only

Not Found

Renewed Unrecorded

Surveyed In Referenced Out

Previous Renewals/Surveys, etc.

1873 Hurlburt 1979 Howard Perry (single Proportioned)

Monument(s) & Accessories Found: (Condition and Source)

Found 2½"Iron pipe with brass cup in a mound of stone to cop

Found 18" Ponderosa Pine Nl8°E-106.5' with open pitched over double blaze marked " $\frac{1}{4}$ \$20BT"

Found 24" ponderosa pine N68°W-150.9' with open pitched over double blaze marked "1/4S19BT"

Found metal fence post with Forest Service Signs 5' south & 5' east of corner Found $\frac{1}{2}$ "IP N14°E- 71.55' from corner

T35R36E WM

1/4

519 | S20 | Fd. 24"

Fd. 24"

Fd. 24"

Fine.

Monument Set (Procedures and Description)

Td. 21/2"I.P.pe with brass

Cup in mound of Stones.

New Accessories

Location & Comments
Red Bridge State Park
Bearings & Distances
by hand compass &
steel tape

Compass Declination

Firm/Agency Oregon State
Parks & Recreation Div.

Address 525 Trade Street SE Salem OR 97310

Party Chief R.Hill Notes R.Hill Witness H.Hanson Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 8, 1988
JOHN E. HOLLINGSWORTH
691

ssworte

(5.)