


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
None

Index File No. W-21



Description of corner evidence found:

No corner monument or other corner evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Cap is stamped;

Set steel fence post 3.0 ft. east of corner.

New BT's;

An 8" Tamarack bears S36.5°W, 53.8 ft., blazed & scribed; N 1/16 S35 BT.

A 10" Tamarack bears S55°E, 56.3 ft., blazed & scribed; N 1/16 S36 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on north slope 75 ft. south of meadow. Road 5160 to Road 5166, 1/2 mi. to 4-way intersection. Dirt track to NW, 1/4 mi to north end of meadow. Corner is NW 300 ft.

I hereby certify the above described corner monument and/or accessories was established as described on August 24, 1984.

T5S R34E
N 1/16
S35 | S36
RLS 1844
1984

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13 1979
DAVID E. SCOTT
1844

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by.....
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 10-17-84
Date Filed 10-24-84
By G. LANGLITZ, DEPUTY
File No. 979-84 R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

W-21


History of original corner establishment:

Corner originally established in 1984 by David E. Scott, PLS 1844, under U.S. Forest Service contract. Scott's notes state:

Set 2.5" aluminum cap on 2 3/8" x 30" aluminum pipe rising 6" above ground. Set steel fencepost 3.0 ft. east of corner.

New BT's:

8" Tamarack bears S36.5°W, 53.8 ft., blazed and scribed: N 1/16 S35 BT.
10" Tamarack bears S55°E, 56.3 ft., blazed and scribed: N 1/16 S36 BT.



Typical USFS Cap

Description of corner evidence found:

Found two bearing trees set by Scott in 1984. No trace of corner monument and fencepost. Corner may have been destroyed by fence building activities.

Remaining Accessories:

A Tamarack, 13" in diameter bears S36.5°W, 53.8' with visible scribing.
A Tamarack, 14" in diameter bears S55°E, 56.3' with no visible scribing.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 3 1/4" aluminum cap on a 2 1/2" x 30" aluminum pipe flush with ground in a small rock collar at record bearing and distance from Scott's bearing trees. Marked as shown in the Corner Diagram.

Set a galvanized steel post 5' east with 54-2 and 54-9 signs.

Bearing trees have 54-3 and 54-9 signs and have a 6" red painted band. The bearing tree face or blaze is also painted red.

Corner monument is 6' south of an east-west fenceline.

Geodetic Coordinates (NAD83):

N 45°05'28.90"

W 118°30'23.25"

Geodetic coordinates were obtained from a Trimble Geo-Explorer mapping grade GPS receiver and have been differentially corrected.

Date: July 10, 2007

Declination: 16°E

Witness: Colin Edwards-Hill

UNION COUNTY SURVEYOR
Date Received 8/16/07
Date Filed 9/17/07
By R. ROBINSON, DEPUTY
File No. 017-2007R

REGISTERED PROFESSIONAL LAND SURVEYOR

Kenneth A. Lind

OREGON
JULY 19, 1994
KENNETH A. LIND
2672

Renews: 12-31-08