## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

G1-25

### History of original corner establishment:

Original Survey by General Land Office contract survey 1884.

The original notes state. Seta post from which; A tamarack 12" in diam bears N70°E 25 lks dist marked 4SBT A tamarack 30" in diam bears S35°W 66 lks dist marked 4SBT;

DIAGRAM	
R35 E	'6s R36EWM
312	57

## Description of corner evidence founds

A tamarack 12" in diam bears N70°E 25 lks dist. Tree in good shape. A tamarack snag 21" in diam bears S35°W 66 lks dist.



# Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a "galvanized pipe 30" long with a bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 30".

I stamped the disk

#COR T6S R35½E | R36E S12 | S7 ORE LIC 381 1969

From the monument the original bearing tree is; A tamarack 12" in diam bears N70°E 25 lks dist. I set the following new bearing tree;

A fir 7" in diam bears 374°W 18.8 ft. dist marked with scribe \$\frac{1}{4}\$SBT and measured to center of tree. I set a steel fence post with USFS sign 54-4 attached. USFS bearing tree signs were placed on the bearing trees shoulder high facing the corner.

		The second secon
Office of County surveyor	County ofUNION	AMON CORALA
for record on the 20. day of Sept	y that the within instance of	SURVEYOR
for record on the20. day of Sept	: 19.69 - 4	led in this office
County surveyor	The state of the s	Date Received
	(DEPUTY)	Date Filed
		11100
		By
		Files Na. 78 41-84R

G-1

Index File No. G-25

#### History of original corner establishment:

Original corner established by Eugene P. McCornack in 1881 under Contract No. 398.

A 4x4 wood post was set, from which: a 12" Tamarack bears N70°E, 25 lks. and a 30" Tamarack bears S35°W, 20 lks.

DIAGRAM T6S R35 1/2E R36E 1/4 12 7

Description of corner evidence found:

Cap is stamped:

1/4 COR

Found 3" brass cap on 2 3/8" iron pipe.

T6S R35 1/2E, R36E

Bearing trees found: 21" W. Larch bears N80°E, 16.7 ft.,

S12 S7

blaze healed, tree in good condition.

ORE LIC 381 1969

21" W. Larch, dead standing, bears S26°W,

13.5 ft., open blaze, scribing visible: 1/4 S BT. 10" Live D. Fir bears S74°W, 18.8 ft., blaze healed, tree is leaning badly.

It appears there is a discrepancy between the bearings Note: measured and indicated on the certificate by LS 381 and my measured bearings to the original bearing trees. Since no original monument was found I have no explanation?

Description of monument and accessories I established to perpetuate the original location of this corner:

Set steel fence post 3 ft. west of corner. The fence post was found south of corner. Since this is an east-west property line, I re-set it on the west side.

New BT's: 11" D. Fir bears S53 1/2°W, 42.2 ft., blazed and scribed: 1/4 S12 BT.

Attached 3/4 brass washer marked RLS 1848 to the lower blazes. Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March 1982.

To find corner, follow USFS Rd 5178080 from 5178 northeasterly 0.5 mi. to where it turns east. The corner is 250 ft. north on the south edge of the area cleared for a fence line, on a slight northerly slope.

Compass Declination: 19 1/2°E Witness: J. Sutton

I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on March 25, 1986.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

Office of	County of	
State of / hereby ce	ertify that the within instrument was fil	ed in this office
for record on the day of		
	by	
(COUNTY OFFICIAL)	(DEPUTY)	-

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

SURVEYOR 5-21-86

UNION COUNTY

Date Filed 5-22-86

BYG. LANGLITZ, DEPUTY File No. 36-86 R