

UNION COUNTY SURVEYOR


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not originally established under GLO Contract

T 3 S R 40 E R - 16

No record of monumentation found in Union County survey records.



DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Union County Minor Partition Plat Number 2004-003T

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8"x30" iron pin 30 inches in the ground, with 2 1/2" aluminum cap marked as shown, from which:

New Bearing Objects:

A 5/8"x30" iron pin with 2" aluminum cap marked "BGB SURVEY MARKER S22 RP" bears North 30°26' West, a distance of 27.37 feet, pin is set in a North-South fence line.

A 5/8"x30" iron pin with 2" aluminum cap marked "BGB SURVEY MARKER S27 RP" bears South 56°09' West, a distance of 16.25 feet, pin is set in a North-South fence line next to the North post of a gate.

Corner falls in the opening for a gate, 13 ft. +/- East of fence corner.

I hereby certify that the corner was monumented on February 19, 2004.


UNION COUNTY SURVEYOR

Date Received 2/23/04

Date Filed 2/24/04

Filed By [Signature]

File Number 001-2004 R



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]
OREGON July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 2004

I used a Leica 530 GPS unit in the establishment of the new accessories. The Basis of Bearing is the same as map of survey number 027-1999. The distances are to the center of a 5/8"x30" iron pin with 1 1/2" aluminum cap.