


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. P-23

History of original corner establishment:

This is not an original GLO corner.



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner set by intersection.  
Set 2.5" aluminum cap on 2.5"x30" aluminum pipe rising 7" above ground. Set steel fence post 3.0 ft. south of corner.

Cap is stamped: T5S R35E  
C1/4•S 24  
RLS 1844  
1985

New BT's:


- 8" Tamarack bears N68 3/4°E, 112.3 ft., blazed and scribed: C1/4 S24 BT.
- 6" P. Pine bears N28°W, 92.2 ft., blazed and scribed: C 1/4 S24 BT.

Corner is found on northeast slope in clearing, 11.0 ft. east of north-south fence. Take Road 51 to Road 5100-223 to Road 5100-229.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Compass Declination: 19 1/2°E  
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 5, 1985.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>9-18-85</u>
☆ GPO-798-276 Date Filed <u>9-23-85</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>59-85R</u>