


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-15

History of original corner establishment:

This is not an original GLO corner.



Description of corner evidence found:

No corner monument or evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by intersection.  
Set 2.5"x30" aluminum capped aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

T5S R35E  
C1/4 S27  
RLS 1844  
1985

New BT's:

- 5.5" W. Larch bears N39°E, 152.3 ft., blazed & scribed: C1/4 S27 BT.
- 5.5" W. Larch bears N46 3/4°W, 62.1 ft., blazed & scribed: C1/4 S27 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "1844" nailed to lower end of blazes.

Corner is in meadow 350 ft. north of Road 5155-040. Take Road 51 to Road 5155, 0.9 miles to Road 5155-040. At top of hill, 0.5 miles, corner is 350 ft. north of road in meadow.

Compass Declination: 19 1/2°E  
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on April 17, 1985.



Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received 9-18-85  
 Date Filed 9-23-85  
 By G. LANGLITZ DEPUTY  
 File No. 71-85 R