


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No U-17



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning.  
Set a 2.5"x30" aluminum capped aluminum pipe rising 7" above ground. Set steel fence post 3.0 ft. east of corner.

T5S R35E  
S1/16  
S27 | S26  
RLS 1844  
1985

New BT's:


- 6" Tamarack bears N84°E, 28.3 ft., blazed and scribed: S1/16 S26 BT.
- 8" Tamarack bears S20°W, 2.3 ft., blazed and scribed: S1/16 S27 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is 15.0 ft. north of east-west fence in bottom of draw, bears NW-SE. Take Road 5155 0.5 miles from Road 51, walk from cattle guard along fence 300 ft. south. Corner is 1350 ft. west.

Compass Declination: 19 1/2°E  
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on April 15, 1985.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>	
Date Received	9-18-85
Date Filed	9-23-85
By	G. LANGRISH, DEPUTY
File No.	78-85R