


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-07

History of original corner establishment:

The original survey of the Standard Parallel along the south boundary of T5S, R35E was by J. Cooper, under Contract No. 397, approved April 5, 1882. At this corner he set a post, from which a 40" Tamarack bears N15°E, 38 lks. and another 40" Tamarack bears N31°W, 68 lks.



Description of corner evidence found:

No corner monument found.

Bearing trees found:

- A 36° tamarack stump bears N31°W, 44.1 ft., scribed (BT).
- A 35" tamarack stump bears N15°E, 21.0 ft. healed blaze.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

Cap is stamped: SC
T5S R35E
1/4, S32
RLS 1844
1984

New BT's:

- A 7" Tamarack bears N46°W, 165.2 ft., blazed and scribed: SC 1/4 S32 BT.
- A 6" Tamarack bears N8.5°E, 76.3 ft., blazed and scribed: SC 1/4 S32 BT.

Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on north slope 460 ft. east of CC 21. Take Rd 5160 to 5160-140 to 5160-142 to 5160-144 to end of road. Go east 120 ft. to fence, north to CC 21, at fence corner. East 460 ft. to 1/4 S32.

I hereby certify the above described corner monument and/or accessories was established as described on September 4, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott
OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 10-17-84
Date Filed 10-24-84
By G. LANGRITZ, DEPUTY
File No. 993-84R

☆ GPO-798-276