

No. 11

Township 3 South

Range 37 East W. M.

Union County, Oregon.

For Ed Staples

Aug 4th 1887

I Commenced at the Corner
to T 2 & 3 S Range 36 & 37 East
from which

a Pin 15 inch base N 54° E 84 No dist

" 12 " " N 62° W 52 " "

" 15 " " S 36° W 31 " "

" 18 " " S 18° E 65 " "

Then South True 20° E

20 00 at Surveyors 1/8 corner

40 52 the 1/4 Sec corner set Sec 1 & 6

from which

I run North on True line

20 26 Set Stone 6 x 6 x 12 inches marked 1/8

from which

a Pin 12 inches base S 14° W 56 No distant

" 14 " " N 52° E 74 " "

40 52 The corner to Sec 1-6-31 & 36 and

T 2 and 3 South of Ranges 36 & 37 East corner

J. W. Kimbrell & Co Surveyors

