

Township 5 South

Range 40 East W.M.

Union County, Oregon.

CHAINS	LINKS	DESCRIPTION
39	70	Thence west on Township line Set Stone 6 x 10 x 23 for corner to Sec 4 = 5 = 32 & 33
		The corner to Sec 3 = 4 = 33 & 34 on Sp line Thence South per 20° E
40	45	found no 1/4 Sec corner
80	75	Intersect 4 lks East of corner to Sec 3 = 4 = 9 & 10 Thence North on line
40	15	Set Post in mound of Stone for 1/4 Sec on lot Sec 3 & 4 Thence west through Sec 4 per 20° E
20	50	Set temporary 1/6 on
40	50	Set temporary center Sec 4
74	97	Intersect at the West Boundary Sec 4 but found no 1/4 Sec corner and proceed to the corner to Sec 4 = 5 = 8 & 9 and run North set Sec 4 & 5 per 20° E
40	50	Set temporary 1/4 Sec corner
80	27	The corner to Sec 4 = 5 = 32 & 33 Thence South
20	33	Set Post for 1/8 corner
40	31	Set Stone 6 x 8 x 24 in for 1/4 Sec corner
80	27	The corner to Sec 4 = 5 = 8 & 9 The 1/4 Sec corner set Sec 4 & 5 - Thence west per 20° E
39	90	Then center Sec 5 Set Post in mound of Stone

W. Kimball Deputy County Surveyor