

Township 8 South Range 46 East W.M. Union County, Oregon.

CHAINS. LKS.

The corner to Sec 4-5-8 & 9

Thence East var 20° E

20 00 Set temporary 1/8 corner

40 00 Set temporary 1/4 Sec cor

60 00 Set temporary 1/8 corner

80 36 The corner to Sec 3-4-9 & 10

Thence West

20 09 Set Post for 1/8 corner from which

an asp 6 inches diameter bears N 87° E 150 lks dist

" " 4 " " " S 53 1/2° W 131 " "

40 18 Set Post for 1/4 Sec cor bet Sec 4 & 9

60 27 Set Post for 1/8 corner

80 36 The corner to Sec 4-5-8 & 9

The 1/4 Sec corner bet Sec 4 & 5-

Thence East through Sec 4 var 20° E

20 50 Set temporary 1/8 corner

40 50 Set temporary center Sec 4

60 00 Set temporary 1/8 corner

79 68 Intersect East boundary 10 lks South of 1/4 Sec cor bet Sec 3 & 4

Thence West

20 05 Set Post for 1/8 corner in center of Sec 4

from which

an asp 5 inches dia. bears N 70° W 71 links dist

" " 6 " " " S 28° E 137 " "

40 11 Set Post for center from which

an asp 3 inches dia. bears N 28° W 17 lks dist

a Pine 30 inches " " S 77° W 258 " "

59 89 Set Post

79 68 The 1/4 Sec corner bet Sec 4 & 5-

The 1/4 Sec corner bet Sec 4 & 3

Thence South through Sec 4 var 20° E

39 75 Intersect E & W line

59 75 Set temporary 1/8 corner

79 85 The 1/4 Sec corner bet Sec 4 & 9

Thence North

20 05 Set Post for 1/8 corner

from which

a Pine 36 inches dia. bears S 63° W 92 lks