

Township

Range

Union County, Oregon.

Hence North 34 1/2 feet Set Stone 4 x 5 x 18 inches Hence North  
417 feet To Place of Beginning in Lobbscharts farm yard

also commencing at a point - 250 Yards North  
of the S E Corner of the S W 1/4 of Section 19  
Set a Stone 8 x 6 x 24 Hence North  
var 20° E

- 10 00 Set Stone 3 x 12 x 18 inches  
Hence North
- 5 00 Set Stone 7 x 11 x 21 inches  
Hence west
- 20 17 Set Stone 3 x 12 x 24 inches  
Hence South
- 5 00 Set Stone 3 x 7 x 18 inches  
Hence South
- 10 00 Set Stone 3 x 10 x 22 inches  
Hence East
- 20 22 To Place of Beginning -

J. W. Kimball County Surveyor