

Township 1 North 41 South

Range 39 East

Union County, Oregon.

- Thence North bet Sec 1 & 2
- 60 45 1/2 Set Stone 7 x 10 x 22 for 1/8 corner  
 50 75 The corner to Sec 1 = 2 = 34 & 36
- The 1/8 corner on West Boundary NW 1/4 Sec 2  
 Thence East through center NE 1/4 Sec 2  
 var 21° E
- 00 50 Set Temporary 1/16 corner  
 80 18 The 1/8 corner on East Boundary NE 1/4 Sec 2  
 Thence West through NE 1/4
- 20 04 1/2 Set Stone 12 x 18 x 26 for 1/16 corner in center NE 1/4 Sec 2
- The corner to Sec 1 = 2 = 11 & 12  
 Thence West bet Sec 2 & 11  
 var 19° E
- 20 50 Set Temporary 1/8 corner  
 40 26 Intersect 26 lbs South of 1/4 Sec corner bet Sec 2 & 11  
 Thence S 89° 38' E on true line
- 20 18 Set Stone 9 x 9 x 31 for 1/8 corner  
 Thence North through SE 1/2 Sec 2  
 var 21° E
- 60 40 The 1/16 corner in center NE 1/4 Sec 2

J. H. Campbell County Surveyor