

Township 7 South Range 45 East Union County, Oregon.

CHAINS. LKS.

The 1/4 Sec Corner bet Sec 24 & 25

Thence North through Sec 24

Var 20° E

20 00 Set Temporary 1/6 Corner

40 00 Set Temporary center Sec 25

81 20 Intersect 61 lks west of 1/4 Sec corner bet Sec 23 & 24 a pine 6 inch dia N 18° E 24 lks dist  
from which a Pine " " S 20° W 27 "

Thence S 26° W on True line

through Center Sec 24

The 1/4 Sec Corner bet Sec 24 & 19 on Range Line from which

an asp 3 inches dia. brs S 4° E 90 lks dist

" 5 " " " S 10° W 87 " "

Thence West through Sec 24

20 00 Var 20° E

20 00 Set Temporary 1/6 corner

39 98 Intersect True N & S line 50 lks North of first Station etc

60 00 Set Temporary 1/6 corner

79 78 Intersect 56 lks South of the 1/4 Sec corner bet Sec 23 & 24 from which

a Pine 5 1/2 inch dia. brs S 33° E 90 lks dist

" 40 " " " N 66° W 165 " "

Thence S 89° 36' E on True line through Sec 24

19 90 Set Post for 1/6 corner in center West 1/2 Sec 24

39 80 Set Post for center Sec 24

59 79 Set Post in mound of Stone for center S 1/2 Sec 24

79 78 The 1/4 Sec Thence South through S E 1/4 Sec 24

Var 20° E

20 00 Set Temporary 1/6 corner

40 44 The 1/8 corner on South Boundary S E 1/4 Sec 24

Thence North through center S E 1/4

20 22 Set Stone 7 x 9 x 18 for 1/6 corner in center S E 1/4 Sec 24

The Center Sec 24

Thence South through S 1/2 Sec 24

20 39 Set Stone 8 x 10 x 17 for 1/6 cor in center S 1/2

from which

a Pine 10 in brs N 78° W 350 lks dist

40 78 The 1/4 Sec cor bet Sec 24 & 25