

1899

191
213

Township 2 South

Range 40 E. W. M.

Union County, Oregon.

CHAINS.	LEGS.	
		Oct. 30 th 1899 Jack Wright Sec. 18-19
		I commenced at the South East Cor of Section 18 and run west
40	00	Set temp $\frac{1}{4}$ Sec. Cor.
60	00	" " $\frac{1}{8}$ " "
80	22	The South West Cor of Sec. 18 making a excess of 72 lks over U. S. G. F. N. then East from S. W Cor Sec 18
19	68	Set $\frac{1}{8}$ Sec. Cor. a marked stone 18x10x4 for corner
39	86	" $\frac{1}{4}$ " " " " " 16x10x6
		Then I commenced at the $\frac{1}{4}$ Sec Cor on West Side Sec. 19 and run East
19	73	Set temp Stake
39	73	" " " "
60	06	The $\frac{1}{8}$ Sec. Cor. set by Kimbrel making a excess of 33 lks U. S. G. F. N. Then back on true line
20	11	Set Cor for center Sec. a rock 12x6x6
40	22	" " " $\frac{1}{16}$ " a stake 4 in. sq.
		Then I commenced at $\frac{1}{4}$ Sec. Cor. on North side of Sec. 18 run West
20	00	Set temp Cor
40	60	North West Cor Sec. 18 making a excess of 85 lks G. F. N. Then I run East
20	20	Set stone in mound for $\frac{1}{8}$ Sec Cor

Arthur Curtis
County Surveyor.