

Township 3 South

Range 37 East

Union County, Oregon.

FAINS. I. K.

John Reed July 26-1902 See 11. the N. 1/2 of N. W 1/4 and N. W 1/4 of N. E 1/4

Commencing at the North East Cor of Sec. 11 T. 3 S. R. 37 East I run West

20 00 Set temp Cor.

40 00 No 1/4 Cor

80 40 The Sec Cor

Then back on true line

60 30 I set 1/8 Sec. Cor. in Mound of Stone

Arthur Curtis

County Surveyor

Town 2 North Range 38 East

J. L. Carter Sec. 16

Commencing at the South East Cor Sec. 16 I run North

40 00 Found 1/4 Sec Cor in place

80 00 " " " " " Then West

40 00 " 1/4 " " " "

80 00 " " " " " " South

40 00 " 1/4 " " " "

60 00 Set temp 1/8 Sec. Cor.

80 00 The South West Cor of Section Then East

40 00 the 1/4 Sec. Cor.

80 00 " South East Cor of Sec. Then from 1/4 Sec Cor on South line of section I run North

20 00 Set stake for 1/16 Cor. Then West

40 00 to 1/8 Sec. Cor. set by me all Gov. Cor are upon the ground and easy found

Arthur Curtis

County Surveyor