




# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
OREGON STATE OFFICE  
P.O. BOX 2965 (825 NE MULTNOMAH STREET)  
PORTLAND, OREGON 97208



RECEIVED

OCT 25 1988

October 21, 1988

Mr. Howard Perry  
Union County Surveyor  
P.O. Box 1107  
LaGrande, OR 97850

Dear Sir:

The enclosed diagram(s) indicate cadastral survey field work completed by this office from October 1987 through September 1988.

The diagram(s) are for informational purposes only. The final field notes and plat have not yet been prepared. If you need any information on any of these surveys, please feel free to contact this office at (503) 231-6987.


Sincerely,

Wayne M. Gardner  
Chief, Branch of Cadastral  
Survey

Enclosures (as stated)

6-X

TOWNSHIP DIAGRAM\*



Field Work Completed During FY 1988

For the Bureau of Indian Affairs,

Umatilla Indian Reservation,  
Umatilla and Union Counties, Oregon

- |  |                                    |
|--|------------------------------------|
| <u>—————</u> Resurveyed or Surveyed line           | 3 1/2 Miles Resurveyed or Surveyed |
| <u>◇</u> Original Corner, previously remonumented  | 42 Monuments set                   |
| <u>◆</u> Original Corner, remonumented this survey |                                    |
| <u>●</u> Corner established this survey            | Group 1343, Oregon                 |
| <u>     </u> Reservation boundary posted           | by Richard L. Johnson              |
| Survey from 10/1/87 to 6/13/88                     |                                    |

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 2 S., R. 34 E., Willamette Meridian, Oregon

CHAINS

27.65 Begin ascent over broken NW. slope.

39.340 Point for the  $\frac{1}{4}$  sec. cor. of secs. 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 2 S R 34 E  
 $\frac{1}{4}$   
S 32 | S 33  
1987

T2S34  
X09

from which

A larch, 15 ins. diam., bears N.  $81^\circ$  E.,  $19\frac{1}{2}$  lks. dist., mkd.  $\frac{1}{4}$  S33 BT.

A larch, 17 ins. diam., bears S.  $15^\circ$  W., 70 lks. dist., mkd.  $\frac{1}{4}$  S32 BT.

Deposit a white "DEEP-1" magnetic marker at the base and set a steel fence post alongside the stainless steel post.

50.260 The original closing cor. of secs. 32 and 33, determined from the remaining original bearing tree:

A fir, 30 ins. diam., bears N.  $5^\circ$  E., 10 lks. dist., with scribe marks 4E S33 on partially healed upper blaze and lower healed blaze. (Record, pine.)

This corner is now amended, no permanent monument established.

50.80 Jeep trail, 15 lks. wide, bears E. and W.

50.90 Barbed wire fence, 4 strands, bears E. and W.

50.940 Intersect the S. bdy. of the Umatilla Indian Reservation.

True point for the closing cor. of secs. 32 and 33, for the north side of the Reservation boundary.

Set a stainless steel post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 2 S R 34 E  
S 32 | S 33  
C | C  
1987

T2S34  
X09I

UNION COUNTY  
SURVEYOR

Date Received 3/8/13

Date Filed 3/8/13

By [Signature] DEPUTY

File No. 234-2013R