

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by David T. Thompson under GLO contract number 103, dated September 3, 1863.

Surveyor's record states:

Set post for 1/4 Sec Corner from which:

A Pine 30 in diam bears S20°E 20 lks dist.

A Pine 20 in diam bears N20°W 10 lks dist.

Survey number 16-79 calls finding a mound of stone and evidence of possible blaze on NW BT. NO MONUMENT WAS SET BY THAT SURVEY.

No record of subsequent monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found no evidence of the original corner monument or it's accessories. Extensive logging has occurred in this area.

See Survey Number 027-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap marked as shown below, 26" in the ground, with ring of stone around monument, from which:

NEW BEARING TREES:


A 11" Douglas Fir bears N 15°E, a distance of 39.58 ft, marked 1/4 S13 BT.

A 7" Douglas Fir bears S 41°E, a distance of 63.65 ft, marked X BT.

A 16" Douglas Fir bears S 2°W, a distance of 62.90 ft, marked 1/4 S24 BT.

A 16" Ponderosa Pine bears N 61°W, a distance of 32.80 ft, marked 1/4 S13 BT.

I hereby certify that the corner was monumented on August 13, 1997.
Witnesses: Jeff Petersen, Jeff Madsen and Greg Blackman Jr.




REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gregory T. Blackman

OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Removal Date: December, 31 1997



**UNION COUNTY
SURVEYOR**

Date Received 8-23-97

Date Filed 8-23-97

Filed By R. Robinson, Deputy

File Number 023-1997R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the bearing tree blaze.