

Township 4 South Range 40 East W.M., Union County, Oregon.

CHAINS. LKS.

40 00 Set Temporary Post for Center Sec 10
80 60 Intersect East Boundary Sec 10 20 lks North of 1/4 Sec corner between Sec 10 & 11

The 1/4 Sec Corner bet Sec 3 & 10
Hence South through Center
Sec 10 Var 20° E

40 26 Intersect E & W line 30 lks East of Temporary Stake
81 47 The 1/4 Sec corner bet Sec 10 & 15 from which

Run North on true line Var 20° E

41 21 Set Stone 10 x 18 x 25 inches marked C.S. for
Center Sec 10

81 47 The 1/4 Sec corner bet Sec 3 & 10

J.W. Kimbrell Deputy Surveyor