


CLAIMS  
LKS.

C. H. Prescott & John Reaves May the 23 1888



I Commenced at The 1/4 Sec Corner bet. Sec 34 & 35  
Thence South bet Sec 34 & 35 Nor 20° E

- 20 00 Set temporary 1/4 corner
- 40 00 Intersect South Boundary 118 lks West of cor to Sec 34 & 35  
Thence North 2° 18' W on True line
- 20 00 Set Post in Mound of Stone for 1/4 cor
- 40 00 the 1/4 Sec cor bet Sec 34 & 35  
The corner to Sec 34 & 35 on 1<sup>st</sup> Standard Parallel South  
Thence East on South Bdy Sec 35 Nor 20° E
- 19 15 Set temporary 1/4 cor on North Bdy Sec 2
- 20 00 Set temporary 1/4 corner on South Bdy Sec 34
- 39 15 Set temporary 1/4 Sec corner on North Bdy Sec 2
- 40 00 found no 1/4 Sec cor on South Bdy Sec 34  
but at 1190 chains further on East I found a Stone marked 1/4
- 59 15 Set temporary 1/4 corner on N. Bdy Sec 2
- 79 15 found no corner to Sec 1 & 2
- 92 15 The corner to Sec 35 & 36  
Thence West
- 111 85 Set Stone in mound of Stone in mound of Stone from Sec 1 & 2

- 29 13 Set Stone in Mound of Stone for 1/8 cor on South Bdy 8 1/4 Sec 35-
- 32 14 Set Post in Mound for 1/8 cor on South Bdy 17 1/4 Sec 2
- 40 25 The 1/4 Sec cor on South Boundary Sec. 35-
- 52 48 Set Post in Mound of Stone for 1/8 cor on North Bdy Sec 2
- 66 20 Set Stone 5x11x32 in for 1/8 cor on East Bdy SW 1/4 Sec 35-
- 72 77 Set Stone for 1/8 cor on N Bdy Sec 2
- 92 15 The cor to Sec 24 & 35-

U.S. Deputy Surveyor John H Stone in September 1875 in Surveying T6 S R 40 E in Closing on the 1<sup>st</sup> Standard Parallel South makes the following Statement

80 78 North along the East Boundary Sec 1 Var 20° 35' E  
Could find no corner

Proceeded to the corner to Sec 34 & 35 on 1<sup>st</sup> Standard Parallel and chained East found no 1/4 Sec corner but at 50 chains I found a Stone marked 1/4 S and at 40 chains further on the corner to Sec 35 & 36 making a mistake of 10 chains in the measurement of the Standard Parallel

Closing Corner north bet Sec 1 & 2 Var 20° E

Intersect 1<sup>st</sup> Standard Parallel South 1185 Chains west of the corner to Sec 35 & 36 marked a Stone 16x15x12 inches marked CC for corner to Sec 1 & 2

North bet Sec 2 & 3 Var 20° E

Intersect 85 chs west of corner to Sec 34 & 35 Set Stone 15x12x11 inch marked CC for corner to Sec 2 & 3

John H. Stone Sept-11 1875 Contract 235-

W.B. Barr U.S. Deputy Surveyor in 1881 claims to have chained the South Boundary of Sec 35 and finds the line to be 80 Chains. as also U.S. Deputy N.O. Waldon in his field Notes in Establishing the 1<sup>st</sup> Standard Parallel South gives the South Boundary Sec 35 as 80 Chains. but I find by careful chaining the South Boundary of the West 1/2 Sec. 35 to 51 chains and 90 links an Error of 1190 chains John H. Barr Deputy County Surveyor

The corner to Sec 35 & 36

Thence North bet Sec 35 & 36 Var 20° 30' E

- 20 00 Set Temporary 1/8 corner
- 44 50 The 1/4 Sec corner bet Sec 35 & 36 Thence South
- 22 00 Set Post in mound of Stone for 1/8 cor

CHAINS	LINKS	
		The 1/4 Sec corner bet Sec 35 & 36 Thence North
43	14	The corner to Sec 25-26-35 & 36 Thence West var 20° E
41	00	The 1/4 Sec corner bet Sec 26 & 35 -
61	00	Set temporary 1/8 cor
93	85	Intersect N & S line 625 links North of corner to Sec 26-27-34 & 35 - Thence N 82° 04' E on true line
26	42 1/2	Set Stone for 1/8 corner
52	85	The 1/4 Sec cor Thence South through Sec 35 - var 20° 15' E
20	00	Set temporary 1/6 corner
40	00	Set temporary center Sec 35 -
60	00	Set temporary 1/6 cor
86	20	The 1/4 Sec corner on South Boundary Sec 35 - Thence North
21	12	Set Stone in mound of Stone for 1/6 corner in Center of Sec 35 -
42	25	Set Stone in mound of Stone for center Sec 35 -
64	33	Set Stake in mound of Stone for 1/6 corner in center N 1/2 Sec 35 -
86	20	The 1/4 Sec corner bet Sec 26 & 35 - The 1/4 Sec cor bet Sec 34 & 35 - Thence East through Sec 35 - var 18° E
20	00	Set temporary 1/6 cor
52	60	The center Sec 35 - Thence west -
26	30	Set Stone in mound of Stone for 1/6 corner in W 1/2 Sec 35 - Thence South
20	62	Set Stone in mound of Stone for center S W 1/4 Sec 35 -
41	25	The 1/8 corner on South Boundary Sec 35 - The corner to Sec 25-26-35 & 36 Thence North var 20° E
20	00	Set temporary post for 1/8 corner
40	50	The 1/4 Sec corner bet Sec 25 & 26 Thence West through Sec 26 var 20° E
40	00	Set temporary center Sec 26
92	87	Intersect N & S line 488 links North of 1/4 Sec cor bet Sec 25 & 26 Thence N 86° 30' E on true line
54	67	The center
92	87	The 1/4 Sec cor The 1/4 Sec corner bet Sec 26 & 35 - Thence North through Sec 26

# RECORD OF SURVEY

05  
1888

Township

Range

Union County, Oregon.

- 20 50 Set Temporary 1/16 corner
- 36 50 Intersect E 1/4 NW line at center
- 50 50 The 1/4 Sec corner bet Sec 23 & 26  
Thence South
- 44 50 The center Sec 26
- 62 25 Set Stone for 1/16 corner in center of Sec 26
- 80 50 The 1/4 Sec corner bet Sec 26 & 35 -  
Thence East
- 20 50 Set Post in mound Stone for 1/8 corner
- The 1/4 Sec corner bet Sec 23 & 26 Thence West over 20° E
- 52 15 Intersect N 1/2 S line 692 lbs North of corner to Sec 22-23-26 & 27  
N 80° 35' E on line
- 52 38 The 1/4 Sec corner bet Sec 23 & 26  
The corner to 34 & 35 on Standard line  
Thence West over 20° 15' E
- 40 15 The 1/4 Sec corner on South boundary Sec 34  
Thence North through Sec 34
- 20 50 Set Temporary 1/16 corner
- 40 50 Set Temporary center Sec 34
- 80 40 Intersect North Edge Sec 34 45 lbs East of 1/4 Sec corner bet Sec 27 & 34  
The 1/4 Sec corner bet Sec 34 & 35 -  
Thence West through Sec 34
- 20 50 Set Temporary 1/16 corner
- 40 36 Intersect N 1/2 S line
- 80 20 The 1/4 Sec corner bet Sec 33 & 34
- 99 84 Set Stone in mound of Stone for center
- 60 02 Set Stone for center E 1/2 Sec 34  
Thence South
- 39 90 Set Stone in mound of Stone for center S E 1/4 Sec 34

J. W. Merrill Deputy County Surveyor