

64
1888

No. 35


Township 4 South

Range 40 East W.M.

Union County, Oregon.

CHAINS. LKS.

Ed Kemilard and John Johnson June 14, 1888
 For the Reestablishment of
 The Corners to Sec 1=12=6 & 7
 5=6=7 & 8 = 7=8=17 & 18
 7=18=12 & 13 and the 1/4 Sec
 corners for Sec 6 & 7 7 & 12
 7 & 8 7 & 18 and the
 Subdivision of Sec 7



I Commenced at the corner to
 T 3 & 4 S Ranges 39 & 40 E which
 is also the corner to Sec 1=6=31 & 36

Thence South on Guide Meridian bet Sec 1 & 6 ¹⁰⁰ 20
 80 00 found no corner Set temporary corner to Sec 1=6=7 & 12

Thence South
 40 00 Set temporary 1/4 Sec cor

60 00 Set temporary 1/2 cor

80 54 a stone marked for cor to Sec 7=18=12 & 13

I Chain on South 4000 Chained and find the corner
 which also proves the correctness of the Stone for corner to Sec 7=18=12 & 13

Thence North

20 07 Set Stone 6x8x20 inch for 1/2 cor

40 14 Set Stone 8x9x23 inch for 1/4 Sec cor for Sec 7 & 12

80 28 Set Stone 10x12x22 inch for corner to Sec 6=7=1 & 12

Thence North

40 14 Set Stone 6x10x20 for 1/4 Sec cor for Sec 1 & 6

80 28 the corner to Sec 1=6=31 & 36

the corner to Sec 7=18=12 & 13

Thence East for Sec 7 & 18 ¹⁰⁰ 20 E

39 80 found no 1/4 Sec cor, Set temporary 1/4 Sec

79 80 found no corner Set temporary 1/2 stone

Thence East

39 93 found no 1/4 Sec cor

39 89 the corner to Sec 8=9=16 & 17

Thence West

39 93 Set Stone for 1/4 Sec cor for Sec 8 & 17

79 87 Set Stone for cor to Sec 7=8=17 & 18

Thence West

40 01 Set Stone for 1/4 Sec cor for Sec 7 & 18

79 81 the corner to Sec 7=18=12 & 13

Township

Range

Union County, Oregon.

- 40 50 The corner to Sec 7=8=17 1/8
 40 50 Set temporary fence North bet Sec 7 & 8
 40 50 Set temporary 1/4 Sec cor
 00 50 Set temporary cor. to Sec 5=6=7 1/8
 Hence North
 00 44 Intersect North Boundary 25 lbs East of cor to Sec 5=6=7 1/8
 Hence South
 00 02 Set Stone 6 x 8 x 30 inches for corner to Sec 5=6=7 1/8
 Hence South
 70 16 Set Post for 1/4 Sec cor bet Sec 7 & 8
 80 32 The cor to Sec 7=8=17 1/8
 The corner to Sec 4=5=8 1/4
 Hence West
 00 47 The corner to Sec 5=6=7 1/8 Hence West
 40 00 Set temporary 1/4 Sec cor
 80 75 The corner to Sec 6=7=17 1/2 Hence East
 40 04 Set Stone 6 x 7 x 18 inches for 1/4 Sec cor bet Sec 6 & 7
 Hence South through Sec 7
 40 00 Set temporary center Sec 7
 00 00 Set temporary 1/16 cor
 80 22 The 1/4 Sec cor bet Sec 7 & 8
 Hence North
 20 06 Set Stone 6 x 5 x 20 inches for 1/16 cor
 40 11 The center
 The 1/4 Sec cor bet Sec 7 & 8
 Hence East through Sec 7
 09 89 The center Sec 7
 74 89 The 1/4 Sec cor bet Sec 7 & 8
 Hence West
 40 18 Set Stone 6 x 12 x 20 inches for center Sec 7
 J. K. Smith & Sons Co Surveyors