

Township 4 South

Range 29 East

Union County, Oregon.

- The $\frac{1}{8}$ corner on West Boundary SW $\frac{1}{4}$ Sec 5 -
 Hence East through center S $\frac{1}{2}$ Sec 5 -
- 27 00 Set temporary $\frac{1}{16}$ corner
 - 49 00 Set temporary $\frac{1}{16}$ corner
 - 60 00 Set temporary $\frac{1}{16}$ corner
 - 51 77 Intersect East Boundary Sec 5 -
 Hence west on 20° E
 - 20 38 Set Post for center S $\frac{1}{2}$ Sec 5 -
 - 40 76 Stone for center S $\frac{1}{2}$ Sec 5 -
 - 61 14 Set Stone for center SW $\frac{1}{4}$ Sec 5 -
 - 81 44 The $\frac{1}{8}$ corner on West Boundary SW $\frac{1}{4}$ Sec 5
- The $\frac{1}{16}$ corner in center SW $\frac{1}{4}$
 Hence North on 20° E
- 14 00 Set Post for Meander No. 1
- The $\frac{1}{4}$ Sec Corner set Sec 5 of 6
 Hence S 74° E
- 20 48 Meander Corner No. 1
 Hence S 79° E
 - 10 00 Set Post for Meander Corner No. 2
 Hence S 83° E
 - 10 30 Set Post for Meander Corner No. 3
 Hence S 85° E
 - 20 25 Set Post for Meander No. 4
 Hence S 78° E
 - 14 00 Set Post for Meander Corner No. 5
 Hence S 24° E
 - 7 00 Set Post for Meander Corner No. 6 388 lks west
 of the $\frac{1}{8}$ corner on East Boundary S $\frac{1}{2}$ Sec 5 -

J. W. Kimbell County Surveyor