

Township 5 South

Range 40 East

Union County, Oregon.

CHAINS
LKS.

The 1/4 Sec corner bet Sec 2 & 3
Hence South var 20° E

20 00 Set temporary 1/8 corner

40 46 the corner to Sec 2-3-10 & 11
Hence North

20 23 Set Post in Mound of Stone for 1/8 corner

40 46 the 1/4 Sec corner bet Sec 2 & 3
Hence East through Sec 2
var 20° E

37 84 Intersect true N & S line 16 lks south of 1st state for center

30 71 the 1/4 Sec corner bet Sec 1 & 2
Hence West

48 87 Set Stone 6 x 8 x 24 in Mound of Stone for Center Sec 2

30 71 the 1/4 Sec corner bet Sec 2 & 3

The 1/8 corner on South Boundary SW 1/4 Sec 2
Hence North 9° W var 20° E

20 00 Set temporary 1/16 corner

40 00 the 1/16 corner point in center W 1/2 Sec 2
Hence South

20 00 Set Stone in Mound of Stone for 1/16 corner in center SW 1/4 Sec 2

J. W. Kimbrell County Surveyor