CORNER REFERENCE INDEX

EXAMPLE

REFERENCE NO.	EXPLANATION
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

10-83R
- 83 — year filed
- 10 — file no.

T 14 , R 39 E

R38E R39E

S25	S30
S36	S31

REFERENCE NO.	NOTES & DESCRIPTION
Survey # 55-79	Found Stone Mound - Set 1½" Pipe in Mound Blackmax-1979

CORNER LOCATION CODE V-1