CORNER REFERENCE INDEX

EXAMPLE

REFERENCE NO.	EXPLANATION
10-83	Refer to Survey Map File
10-83N	Refer to Narrative File
10-83R	Refer to Corner Restoration File

10-83R
- 83 — year filed
- 10 — file no.

T 1S, R 40 E

S14	S13
S23	S24

REFERENCE NO.	NOTES & DESCRIPTION	
SURVEY # 11	SET 1¼" PIPE	SLAGHT - 1957
SURVEY #59-75	CORNER DESTROYED - SET 2" PIPE	
	W/BRASS CAP	HAMBLETON - 1975
020-2022R	MONUMENTATION RECORD	HSU - 2022
GPS 20220019	GPS OBSERVATION	HSU - 2022

CORNER LOCATION CODE N 21