


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-2

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner set from survey by single proportionate measurement.

At the corner point, we set a 2"x30" Galvanized Iron Pipe, 20" in the ground to bedrock, and in a mound stone, 4 ft. diam. to top of pipe, with a brass cap attached, stamped:

From which we mark new BT's:

A 16" Douglas Fir, scribed "W 1/16 S6 BT" on a double blaze bears S30 1/2°E 66.3 ft.

And a 12" Larch, scribed "W 1/16 S31 BT" on a double blaze bears N 50°E 75.2 ft.

Attached brass washer, marked "LS 1099" to lower blaze of each BT .

Placed steel fenceposts 5 ft. S and E of monument with signs 54-2 and 54-3 attached to southerly post and sign 54-2 only on easterly post.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, Oct. 1979.

T2N
31
W 1/16 ——— R38E
6
T1N
PLS1099
1980

Compass Declination: 18° East

I hereby certify that the above described corner monument and/or accessories was established on Oct. 10, 1980.

Witness: John Curtiss

REGISTERED PROFESSIONAL LAND SURVEYOR

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... County Surveyor..... County of..... Union
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL)

UNION COUNTY
SURVEYOR
(DEPUTY)

Received _____
Date Filed _____
By _____
File No. 1-84 R