CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-23

History of original corner establishment:

Corner originally established in 1881 by Jacob C. Cooper under \S Government Contract No. 397. Surveyor General Notes state:

Set post 3 ft long 3" square 18 " in ground marked 45 on North and South faces for 4 section corner on west side of mountain 20 ft above bottom of dry ravine

A pine 14" in diameter bears S 60 W 26 links dist. marked 4 S BT.

7-23 DIAGRAM T2N R38E TIN R 38 E

No record of re-survey found in County Records.

Description of corner evidence found:

Found:

A 30" pine S 60 W, 26 links, dead, standing, scribes visible


Description of monument and accessories I established to perpetuate the original location of this corner:

I set a $2^{1}2^{11} \times 30^{11}$ galvanized iron pipe with brass cap marked as shown at the record bearings and distance from BT, 27" in the ground. From which, New BTs:

A douglas fir, 20" diameter bears \$ 89° E, 3 ft dist.

marked T1N R38E $\frac{1}{4}$ S1 BT A douglas fir, 14" diameter bears N 30° W, 12.8 ft dist. marked T2N R38E 4 S36 BT





I used a steel tape and a magnetic compass with 20° E declination.

I set a brass washer marked O.P.L.S. 991 at the B.T. blaze.

Office of County of		
State of		UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Date Received
		By

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Jacob Cooper under GLO contract number 397 dated July 1, 1881. Surveyor General field notes state:

Set post 3 foot long, 3" square, 18" in ground marked 1/4S on North and South faces for 1/4 section corner on west side of mountain, 20 ft. above bottom of dry ravine from which:

A Pine 14" in diameter S 60° W 26 lks dist

S 1

T1N R38EA-23

In 1980 Greg Blackman found the bearing tree. Union County Monumentation Record 16-84R states: I set a 2 ½" x 30" galvanized iron pipe with brass cap marked as shown at the record bearings and distance from BT, 27" in the ground, from which:

Found: A 30" pine S 60° W, 26 links, dead, standing, scribes visible

And New BT's:

A Douglas Fir, 20" diameter bears S 89° E, 3 ft. dist. marked T1N R38E 1/4 S1 BT. A Douglas Fir, 14" diameter bears N 30° W, 12.8 ft. dist. marked T2N R38E 1/4 S36 BT

DESCRIPTION OF CORNER EVIDENCE FOUND:

A 2 ½" galvanized iron pipe, 6" above ground, with brass cap marked as shown below, from which:

A 30" Ponderosa Pine bears South 60° West, a distance of 17.16 feet, alive and vigorous with

scribes visible on an opened blaze. A 28" Douglas Fir bears South 89° East, a distance of 3 feet, alive and vigorous with healed

A 20" Douglas Fir bears North 30° West, a distance of 12.8 feet, alive and vigorous with healed blaze.

A fence post with monumentation signs bears West uprooted and down on the ground.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the brass cap monument:

NEW BEARING OBJECTS:

A 13" Douglas Fir bears North 8° East a distance of 12.35 feet, marked 1/4 S36 BT.

Reset fence post approx. 3 feet West.

I hereby certify that the corner was perpetuated on May 05, 2020.

Witness: Kyle A. Tucker

REGISTERED **PROFFSSIONAL** LAND SURVEYOR

OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

R38E T2N S36 1/4 S1 **R38E** T₁N 1980 **OPLS** 991

UNION COUNTY **SURVEYOR** Date Received 6 1 7070

File Number <u>640</u>

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.