


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-2

History of original corner establishment: None



Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner: Corner set from survey at location determined by subdivision of section.

At the corner point we set a 2"x30" galvanized iron pipe, 26" in the ground on a steep East slope, with brass cap attached, marked:

T1N R38E
 S7
 C —|— C
 W 1/16
 PLS 1099
 1980

From which we mark new BT's:

A 12" Larch, scribed "CW1/16 S7 BT" on a double blaze bears N54½°W 67.3 ft.,

A 12" White Fir, scribed "CW1/16 S7 BT" on a double blaze, bears S56°W 24.5 ft.

Attached brass washer marked "LS 1099" to lower blaze of each BT.

Placed steel fenceposts 5 ft. S and E of monument with signs 54-2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey U.S.F.S. Region 6, October 1979.

I hereby certify that the above described corner and/or accessories was established on October 10, 1980.

Compass Declination: 18° East

Witness: John Curtiss

REGISTERED PROFESSIONAL LAND SURVEYOR

Gary L. Langlitz
OREGON
 JULY 22, 1977
GARY L. LANGLITZ
 1089

Office of..... County Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received.....
 Date Filed.....
 By.....
 File No. 47-84 R