


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-4

History of original corner establishment: None



Description of corner evidence found: A steel fencepost, unmarked, bears N10°W 15.0 ft. from the corner described below. Refer to Record Survey No. 23-1964 on file in the office of Union County Surveyor.

**Description of monument and accessories established to perpetuate the**

**original location of this corner:** Corner set from survey by subdivision of section. At the corner point, we set a 2"x30" galvanized iron pipe, 26" in the ground, with brass cap attached, marked:

T1N R38E

From which we mark new BT's:

S7 C — C E1/16

An 8" Grand Fir, scribed "CE 1/16 S7 BT" on a double blaze bears S82°W 12.6 ft.

PLS 1099  
1980

A 16" Spruce, scribed "CE 1/16 S7 BT" on a double blaze bears N12½°W 25.0 ft.

Attached brass washers, marked "LS 1099" to lower blaze of each BT.


Placed steel fenceposts 5 ft. N and E of monument with signs 54-2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications For Cadastral Survey, U.S.F.S. Region 6, October 1979.

I hereby certify that the above described monument and/or accessories was established on October 13, 1980.

Compass Declination: 18° East

Witness: John Curtiss



Office of..... County Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

★ GPO—798-276

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 49-84 R