


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. H-2

History of original corner establishment: None



None.

Description of corner evidence found: None

None.

Description of monument and accessories I established to perpetuate the

original location of this corner: Corner set from survey by subdivision of section.

At the corner point, we set a 2"x30" galvanized iron pipe, 26" in the ground on a steep N slope, with brass cap attached, marked:

From which we mark new BT's:

A 10" Grand Fir, scribed "SW 1/16 S7 BT" on a double blaze bears N70°E 15.0 ft.

A 24" Grand Fir, scribed "SW 1/16 S7 BT" on a double blaze bears N56°W 15.6 ft.

T1N R38E

S7

+

SW 1/16

PLS 1099

1980

Attached brass washer, marked "LS 1099" to lower blaze of each BT.

Placed steel fencepost 5' N and E of monument with signs 54-2 and 54-9 attached. Attached signs and painted BT's per Standard Specifications For Cadastral Survey, U.S.F.S. Region 6, October 1979.

I hereby certify that the above described corner and/or accessories was established on October 13, 1980.

Compass Declination: 18° East

Witness: John Curtiss



Office of..... County Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____
 ☆ GPO—750-276

Date Filed _____

By _____

File No. 54-84 R