


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. H-5

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner set from survey by single proportionate measurement

At the corner point, we set a 2"x30" Galvanized Iron Pipe 25" in the ground, with brass cap attached, marked:


From which we mark the following BT's:

A 10" White Fir, scribed "S 1/16 S7 BT on a double blaze bears N45 1/2°W 26.7 ft., and a 12" Larch, scribed S 1/16 S8 BT" on a double blaze bears N71°E 53.0 ft.

Attached brass washer, marked "LS 1099" to lower blaze of each BT.

Placed steel fenceposts 5 ft. S and W of monument with signs 54-2 and 54-9 attached to southerly post and 54-2 to westerly post.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, Oct. 1979.



I hereby certify this corner monument was established as herein described on Oct. 3, 1980.

Compass Declination: 18° East

Witness: John Curtiss

Office of..... County Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL)

REGISTERED PROFESSIONAL LAND SURVEYOR

Gary L. Langlitz
OREGON
 JULY 22, 1977
GARY L. LANGLITZ
 1099

UNION COUNTY SURVEYOR

Date Received _____
 Date Filed _____
 By _____
 File No. 56-84B

☆ GPO-798-276