


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 1 N R 38 E L-19



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 008-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At the position by survey I set a 2 1/2" x 30" aluminum pipe, 22" in the ground, in a mound of stone 3' with 3" aluminum cap marked as shown below, from which:

NEW BEARING TREES:

- A 6" Douglas Fir bears North 43° East a dist. of 17.15 ft., marked C 1/4 S14 BT.
- A 9" White Fir bears South 75° East a dist. of 32.70 ft., marked C 1/4 S14 BT.
- A 10" White Fir bears South 22° West a dist. of 21.15 ft., marked C 1/4 S14 BT.
- A 13" Western Larch bears North 54° West a dist. of 37.50 ft., marked C 1/4 S14 BT.

Set steel fence post approx. 2' North.

East/West running fence bears North of monument approx. 40 ft.

I hereby certify that the corner was monumented on May 9, 2019.

Witness: Kyle A. Tucker.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

BAGETT - GRIFFITH & BLACKMAN

T1N R38E

C 1/4 S14

2019

OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 5/14/19

Date Filed 5/14/19

Filed By MLG/hsu

File Number 028-2019R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. The bearings are to a brass washer marked OPLS 83571 attached to the BT blaze of the new bearing trees.