


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

T 1 N R 38 E O-09



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 018-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:

An 11 inch Douglas Fir bears South 32° East, a distance of 48.25 feet, marked N1/16 S21 BT.
An 8 inch Lodgepole Pine bears South 55° West, a distance of 45.65 feet, marked N1/16 S20 BT

Corner falls approximately 1 foot North of the centerline of an East/West running logging road.

I set a steel fencepost approximately 5.7 foot North of corner monument.

I hereby certify that the corner was monumented on July 8, 2014.

Witness: Thomas J. Kopp

<p>REGISTERED PROFESSIONAL LAND SURVEYOR</p> 
<p>OREGON June 2, 2010 JEFFREY S. HSU 83571</p>

Renewal Date: June 30, 2015

<p>UNION COUNTY SURVEYOR</p>
<p>Date Received <u>7/11/14</u></p>
<p>Date Filed <u>7/11/14</u></p>
<p>Filed By <u>[Signature]</u></p>
<p>File Number <u>028-2014R</u></p>

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike in the right hand side of the bearing trees. Bearings are to a washer marked OPLS 83571 set in the upper portion of the BT blaze.

O-09