


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

None.

T 1 N R 38 E Q-22



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

SEE SURVEY NUMBER 008-2019

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**

At the position by survey I set a 5/8"x18" iron pin, drilled 8" into bedrock, with 2 1/2" aluminum cap marked as shown below, in a collar of stone 2' diam, from which:

**NEW BEARING OBJECTS:**

A 5/8"x15" iron pin bears West, a distance of 10.00 feet, with 1 1/2" aluminum cap marked W RP.

A 5/8"x15" iron pin bears North 0°16' East, a distance of 23.00 feet, with 1 1/2" aluminum cap marked N RP.

Fence corner from which fences bears North, South and West falls South of monument approximately 50 feet. North/South fenceline falls West of monument approx. 2 ft.


I hereby certify that the corner was monumented on May 7, 2019.

Witness: Kyle A. Tucker.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2019



**UNION COUNTY  
SURVEYOR**

Date Received 5/14/19

Date Filed 5/14/19

Filed By Nick Gilman

File Number 032-2019R

I used a Leica GS 18 RTK GPS in the establishment of the accessories. Basis of Bearing is as per Survey 008-2019. Bearings and distances are to the center of the aluminum cap.