



Land Surveying &  
Boundary Consulting

P.O. Box 19  
Mill City, OR 97360  
(503) 897-2722

**CERTIFIED RECORD OF LAND  
CORNER MONUMENTATION**

**History of original corner establishment:**

**Howard L. Perry, PLS 1294, 1980, C.S. 38-80**  
*Set: 5/8" x 30 rebar with yellow plastic cap marked AP & A*

**Gary L. Langlitz, PLS 1099, 1995, C.S. 35-95**  
Monument set by Survey 38-80 not found.  
*Set: 5/8" x 30" iron rod (concrete reinforcing rod) with yellow plastic cap marked AP & A.*

**Description of corner evidence found:**

***Monument Found:***

A 5/8" rebar with plastic cap marked A P & A. Searched a 15 ft. radius around existing rebar for missing rebar, nothing found.

***Accessories Found:***

None set previously, none found.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

***Monument Set:***

Replaced plastic cap with a 3 1/4" aluminum cap marked as shown. The new cap was placed on the existing rebar.

***Accessories Set:***

A white fir, 10 ins. diam., bears N 6 1/2° E 27.50 ft., marked E 1/16 S32 BT on a double blaze.

A Douglas fir, 19 1/2 ins. diam., bears N 88 1/2° E 40.27 ft., marked E 1/16 S32 BT on a double blaze.

Red paint, posts and signs added as needed.

***NAD 83 (CORS 2002) Coordinates:***


Geographic	State Plane (North Zone)
45°30'52.7926" N	N 208,180.612 Meters
118°04'55.6981" W	E 2,688,881.645 Meters
Convergence 1° 42'53"	

***Equipment:*** Staff compass, Var. 18° E, logger's tape, clinometer

***Date:*** August 7, 2003

***Crew:*** Dick Chesebro

***See also the Record of Survey filed concurrently with this certification.***



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Evelyn R. Kalb 7/19/04*

OREGON  
July 25, 1990  
Evelyn R. Kalb  
2456

EXPIRES: 06/30/2005

**UNION COUNTY  
SURVEYOR**

Date Received 2/3/04  
Date Filed 2/25/04  
Filed By R. Robinson, Deputy  
File Number 009-2004R