


RECOVERY NOTES
BOISE CASCADE CORP.
PROPERTY CORNER INVESTIGATION

G-1
LOCATION



T. 1N R. 39E
Mer. WM State OR
Forest _____ Dist. Elgin
Compartment or Tract G-P

LEGEND

- Corner searched-no evidence
- ⊗ Corner or accessory found
- Corner marked by perm. mon.

DESCRIPTION OF FOUND CORNER

MATERIAL: Rock pile SIZE: _____
HEIGHT ABOVE GROUND: _____ CONDITION: _____
MARKINGS: Painted yellow

DESCRIPTION OF FOUND ACCESSORIES

PP in SE quadrant is present and alive, seriously visible it will be high stumped during logging in 1984 - tag on tree now.
SW BT is present as a decaying log on the ground

Note: Indicate full investigative details on back of form and where cruise tag placed in reference to corner.

PHOTO IDENTIFICATION

Symbol & date 82 Line or Roll 13 Exposure 6
How Identified punched Where filed Elgin

RECOVERED BY: D. Morrison
DATE: 6/18/84 TITLE: Forester

UNION COUNTY
SURVEYOR

Date Received 1-4-88

Date Filed 1-7-88

By G. LANGLITZ, DEPUTY

File No. 21-88R

G-1