


**UNION COUNTY SURVEYOR**

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

No record of monumentation found in Union County survey records.

T 1 N R 39 E L-09



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

NONE

See Survey Number 025-1998

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position determined by the survey I set a 2 1/2" x 30" aluminum pipe with cap 26 inches in the ground, marked as shown, from which:

**NEW BEARING OBJECTS AND TREES:**

A 12 inch Dia. Douglas Fir bears N 45° E, a distance of 25.26 feet, marked 1/4 S16 BT

A 13 inch Dia. Douglas Fir bears S 70° E, a distance of 14.92 feet, marked 1/4 S16 BT

A 15 inch Dia. Douglas Fir bears S 53° W, a distance of 35.70 feet, marked 1/4 S17 BT


An 11 inch Dia. Douglas Fir bears N 84° W, a distance of 10.95 feet, marked 1/4 S17 BT

I hereby certify that the corner was monumented on August 5, 1998.  
Witness: Jeff Madsen, Greg Engelgau, and Norb Volny.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
July 17, 1986  
RICK G. ROBINSON  
2219

Renewal Date December 31, 1998



**UNION COUNTY SURVEYOR**

Date Received 8/10/98

Date Filed 8/29/98

Filed By [Signature]

File Number 022-1998R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination. Distances are to a 60d spike driven into the root crown of the bearing tree in the right side. A brass washer marked OPLS 2219 was attached to the BT blaze.