UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 033-2004 DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: At position determined by survey, I set a $5/8\text{"} \times 30\text{"}$ iron pin with 2 ½" aluminum cap, marked as shown, 28 inches in the ground from which:

T1N R39E P-11 S 21

NEW BEARING TREES:

A 6 inch diameter Ponderosa Pine bears N 21° E, a distance of 36.35 feet, marked X BT

A 12 inch diameter Ponderosa Pine bears S 56° E, a distance of 18.42 feet, marked C1/4 S21 BT

A 6 inch diameter Ponderosa Pine bears S 6° W, a distance of 5.24 feet, marked X BT

A 9 inch diameter Ponderosa Pine bears N 53° W, a distance of 6.31 feet, marked C1/4 S21 BT

Set steel fence post approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on October 19, 2004.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON

RICK G. ROBINSON 2219

Renewal Date December 31, 2004



UNION COUNTY SURVEYOR

Date Filed

052-2004R File Number

I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 18° East magnetic declination and the distance is to a 50d nail set in the right side of the root crown. I set a brass washer marked OPLS 2219 on the BT blaze.