
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 022-1998.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 $\frac{1}{2}$ " diameter 30" long aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, with a ring of stone around cap, from which:

NEW BEARING TREES:

A 23" diameter Ponderosa Pine bears N 73° E, a distance of 54.48 feet marked CS 1/16 S12 BT.

A 14" diameter Douglas Fir bears N 67° W, a distance of 14.53 feet marked CS 1/16 S12 BT.

I hereby certify that the corner was monumented on July 9, 1998. Witness: Norbert Volny, Jeff Madsen.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1996
RICK G. ROBINSON
2219


Renewal Date December 31, 1998

UNION COUNTY
SURVEYOR

Date Received 7/20/88

Date Filed By Syran I Arghur

File Number 0/4-1998 R



I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 17° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. attached a brass washer marked OPLS 2219 to the BT blaze.