CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

5-11 DIAGRAM 2N 3BE CN1/16 28

Description of corner evidence found:

N/A

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
JAMES H. BUISMAN
1097

TZN

CN /16

1238E

28

1097

1980

Description of monument and accessories t established to perpetuate the original location of this corner

At the position described above, I set a $2\frac{1}{2}$ " aluminum cap on a $2\frac{1}{2}$ " x 30" aluminum pipe 26" in the ground marked as shown.

From which I scribed BTs:

A fir 11" in diam. bears N $11^{\circ}30'$ W 25.5' scribed CN 1/16 S 28 BT. A spruce 17" in diam. bears N $76^{\circ}18'$ E 48.6' scribed CN 1/16 S 28 BT.

I nailed a brass washer marked OPLS 1097 to BT blazes.

I set a steel fence post 5' North with signs 54-2 and 54-4.

I set a fiberglass fence post 5' East with signs 54-2.

I painted a red band around BTs and face of scribe.

I used a steel tape and Wild T-2 and measured a horizontal distance to the center of the BTs .

This corner was set October 28, 1980. Witness by Patrick L. Murphy.

See map of survey.

Office of	County of	
State of , I hereby certify t		
for record on the day of		
Ь	•	
(COUNTY OFFICIAL)	(DEPUTY)	LINION

Form R6-7100-57 (9/71)

UNION	RAEAQB SAEAQB
Date Receiv	ed
Date Filed_	
Ву	@ GPO 796-333