CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

1/4 corner common to Sections 13 & 24, T2N, R39E, W.M., Union County, Oregon.

Original corner established in 1881 by R. Moore under contract No. 382 approved 3/23/1881. He set a basalt stone 14"x10"x6" and no original references.

Description of corner evidence found:

No original corner evidence found.

REGISTERED PROFESSIONAL LAND, SURVEYOR

OREGON
JULY 12, 1979
B. A. SUTTON
1848

RENEWAL 6/30/98

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 2-1/2"x30" aluminum capped aluminum pipe marked: at the proportioned location between the Section corners East and West of this corner.

T2N R39E S13 1/4 S24 RLS 1848 1987

I established the following references:

A 15" Ponderosa Pine bears N3°15'E, 151.6' blazed & scribed (1/4S13BT)

A 22" Ponderosa Pine bears S67°30"W, 91.9' blazed & scribed (1/4S24BT)

Office of the County Surveyor	County of	
State of Oregon, I hereby certify that the within instrument was filed in this office		
for record on the day o	f, 19	10/20/96
by		10/2018 2
(COUNTY OFFICIAL)	(DEPUTY)	11/14/96
	 	Jug 7 Duc
		111-1996R