
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T2N R40 EL-14



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 029-2022

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey, I set a 5/8" x 30" iron pin, 24" in the ground, with 2 1/2" aluminum cap marked as shown and in a 2 ft. diam. collar of stone, from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears North 0°09' East a dist. of 30.00 ft., marked "N RP BGB SURVEY MARKER" A 5/8" x 30" iron pin bears North 43°06' West a dist. of 30.00 ft., marked "NW RP BGB SURVEY MARKER"

Set steel fencepost approx. 0.5 ft. Northwest

Fence corner to North/South/West bearing fencelines bears approx. 80 ft. Southeasterly

I hereby certify that the corner was monumented on September 7, 2022. Witness: Dan S. Drum, Kyle A. Tucker

GRIFFITH 84 8 A T2N R40E W 1/16 **S15 OPLS 83571** 2022

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON

JEFFREY S. HSU 83571

Renewal Date: June 30, 2023

I used a Leica GS18 RTK in the establishment of the new accessories. Basis of Bearing is as per Survey Number 029-022. Distances and bearings are to the centers of the aluminum caps.

UNION COUNTY SURVEYOR