## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Rufus S. Moore under GLO contract number 382, dated March 23rd, 1881. GLO record states:

Set post for 1/4 Sec Cor from which:

A Pine 24 in diam bears N 23° E 73 lks dist A Pine 26 in diam bears S 57° W 31 lks dist

No record of subsequent monumentation found in UNION COUNTY survey records.

T2N R40E T-13 S 28

See Union County Survey Number 023-1998

Found 26 in. Pine snag, S 57° W 31 lks. Dead and standing with blazes open and burnt.

Found badly rotted stump N 23° E 73 lks. Very rotted , no scribes visible.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At record bearing and distance from the found bearing tree and rotted stump, I set a 2  $\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap 28" in the ground, from which:

A 10" Ponderosa Pine bears N 58° E, a distance of 51.62 feet, marked X BT An 11" Ponderosa Pine bears S 9° E, a distance of 29.70 feet, marked 1/4 S27

 $\bar{\text{A}}$  16" Tamarack bears S 42° W, a distance of 34.30 feet, marked 1/4 S28 BT. An 18" Ponderosa Pine bears N 64° W, a distance of 84.70 feet, marked 1/4 S28 BT.

I hereby certify that the corner was monumented on July 10, 1998. Witnesses: Greg Blackman Jr.and Norb Volny

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON

GREGORY T. BLACKMAN 991

1. Blee A

Ronewal Date: December, 31 1999

SURVEYOR COUNTY 3 NO M **T2N R40E** 1/4 **S27 S28** 1998 **OPLS 991** 

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 19° East declination, the distances are to a 60d spike driven into the right side of the root crown of the new bearing trees. A brass washer marked OPLS 991 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR

Date Filed \_\_\_

Filed By R. RUBINSON, DEDUTY

T-13