


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Y-15

History of original corner establishment:


None.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:



At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 12" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E;

An 11" pine bears N15°W, 30.4 ft. scribed CS1/16S34 BT. A 13" pine bears S08°W, 72.6 ft. scribed CS1/16S34 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051. Placed 54-2 and 54-9 on steel fence post 5' east and 54-2 on steel fence post 5' north of the corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Doug Moser
Ron Gilroy

November 4, 1980

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of County Surveyor..... County of Union.....
State of Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 30th day of January....., 1981

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Received _____

★ GPO—798-278

Date Filed _____

By _____

File No. 196-84R