


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. X-Y-15

History of original corner establishment:

None.



Description of corner evidence found:

None Set.

Corner is about 50' north of track road.

Description of monument and accessories established to perpetuate the original location of this corner:


At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 20" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E:

A 13" pine bears S44°E, 34.7 ft. scribed ULRCS34CC BT.

A 13" pine bears S50°W, 16.0 ft. scribed ULRCS34CC BT.

Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5' east and 54-2 on steel fence post 5' south of the corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Doug Moser
Ron Gilroy

November 4, 1980

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

REFER TO SURVEY 10-81

Office of... County Surveyor..... County of... Union

State of... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 30th day of... January....., 19.81

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

NARRATIVE DRAWER 1/3

UNION COUNTY SURVEYOR

Date Received 790-276 3/12/13

Date Filed 3/12/13

By J/Y & L DEPUTY

File No. 289-2013R