History of original corner establishment: Not established during original survey.

Index	File	No. E-8	
DIAGRAM			
	T2S	R36 E	
E 1/	16 <u>S</u>	5 8	

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:	
Corner location determined by single proportionate measurement N 1/4 Corner and the NE corner of Section 8.	between the
At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap stamped:	T2S R36E S5
Set pipe 22" in ground with mound of stone and dirt to cap	E 1/16
Bearing trees:	OR PLS 1099
A Grand Fir 7" dia. bears N 63° E, 15.0 ft. scribed E 1/16 S A Grand Fir 8" dia. bears S 9° E, 12.6 ft. scribed E 1/16 S Attached 54-3 and 54-4 signs to both BT's and brass washer stan LS1099 to foot blaze of both BT's. Painted blazes and 6" band both BT's red. Attached 54-2, 54-4 and 54-9 signs to metal pos West of corner. Corner falls on Northeast slope in thick stand of Grand Fir ft. East of location tag for N 1/4 Cor. S8 on wood post on West dirt road w/location tag marked 430 ft. West to S5 1/4 -+ T2S R36 Compass Declination: 18 1/2° East S8 I hereby certify the above described corner monument and/or accessories was established as described on October 13, 1981. Witnesses: Rodger Orton Jeff Anderson	B BT. aped around st 6 ft. and 930 side of N-S E REGISTERED PROFESSIONAL LAND SURVEYOR JULY 22, 1977 GARY L. LANGLITZ
State of Oregon , I hereby certify that the within instrument was filed in for record on the 4 day of OctoBER , 1982 Howard L. Perry by Der J. Jana Jana	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Received ☆ GPO 759-509
	Date Filed
	Ву
	File No. 231-84 R